


Martin[®] QC1™ Cleaner HD STS

Go to Martin[®] QC1[™] Cleaner HD STS web page





Operator's Manual M4043

Important

MARTIN ENGINEERING HEREBY DISCLAIMS ANY LIABILITY FOR: DAMAGE DUE TO CONTAMINATION OF THE MATERIAL; USER'S FAILURE TO INSPECT, MAINTAIN AND TAKE REASONABLE CARE OF THE EQUIPMENT; INJURIES OR DAMAGE RESULTING FROM USE OR APPLICATION OF THIS PRODUCT CONTRARY TO INSTRUCTIONS AND SPECIFICATIONS CONTAINED HEREIN. MARTIN ENGINEERING'S LIABILITY SHALL BE LIMITED TO REPAIR OR REPLACEMENT OF EQUIPMENT SHOWN TO BE DEFECTIVE.

Observe all safety rules given herein along with owner and Government standards and regulations. Know and understand lockout/tagout procedures as defined by American National Standards Institute (ANSI) z244.1-1982, *American National Standard for Personnel Protection - Lockout/Tagout of Energy Sources - Minimum Safety Requirements* and Occupational Safety and Health Administration (OSHA) Federal Register, Part IV, 29 CFR Part 1910, *Control of Hazardous Energy Source (Lockout/Tagout); Final Rule.*

The following symbols may be used in this manual:



Danger: Immediate hazards that will result in severe personal injury or death.



Warning: Hazards or unsafe practices that could result in personal injury.



Caution: Hazards or unsafe practices that could result in product or property damages.

IMPORTANT

Important: Instructions that must be followed to ensure proper installation/operation of equipment.



Note: General statements to assist the reader.

Table of Contents

| Section | Page |
|--|------|
| List of Figures/Tables | ii |
| Introduction | 1 |
| General | 1 |
| Installations Without Chutework | 1 |
| Belt Cleaner Inspection Access | 1 |
| References | 1 |
| Materials required | 1 |
| Urethane Shelf Life | 2 |
| Safety | 3 |
| Before Installing Belt Cleaner | 4 |
| Installing Belt Cleaner | 7 |
| Locating Cleaner Centerline | 7 |
| Marking Chute Cutouts | 8 |
| Installing Spring Tensioner | 9 |
| Installing Air Cylinder Tensioner | 10 |
| Installing Belt Cleaner | 12 |
| After Installing Belt Cleaner | 13 |
| Maintenance | 14 |
| Blade Servicing | 14 |
| Troubleshooting/Installation Checklist | 17 |
| Part Numbers | 18 |

List of Figures

Title

| Figure | Title | Pag |
|--------|---|------|
| 1 | Belt Cleaner Mounting Locations | 5 |
| 2 | Belt Cleaner Location | 7 |
| 3 | Operator Side Chute Cutout | 8 |
| 4 | Far Side Chute Cutout | 8 |
| 5 | Adjusting Spring Tensioner | |
| 6 | Air Cylinder Schematic | 10 |
| 7 | Installing Belt Cleaner | 12 |
| 8 | Blade Replacement. | 15 |
| 9 | Martin [®] QC1 [™] Cleaner HD STS Assembly, P/N STSHDQC-XXXXXXX | XX19 |
| 10 | Martin [®] Air Cylinder Tensioner HD STS, P/N 39100-HDA | 21 |
| 11 | Martin [®] Spring Tensioner HD STS, P/N 39100-HDS | 23 |
| 12 | Conveyor Products Warning Label, P/N 23395 | 25 |
| 13 | Pinch Point Warning Label, P/N 30528 | 25 |
| 14 | Martin [®] Spring Tensioner HD STS Tensioning Label, P/N 39437-S | 26 |
| 15 | Martin [®] Air Tensioner HD STS Tensioning Label, P/N 39437-A | 26 |

List of Tables

| Table | Title | Page |
|-------|---|------|
| Ι | Martin [®] QC1 TM Cleaner HD Blade Colors, Materials and Specifications | 2 |
| II | Urethane Shelf Life | 2 |
| III | Spring Tensioner Settings | 9 |
| IV | Air Cylinder Tensioner Settings | 11 |
| V | Martin [®] QC1 TM Cleaner HD STS Assembly Part Numbers | 20 |

Introduction

| General | To introduce product back into the product flow, the Martin [®] QC1 TM Cleaner HD STS is installed on the face of the head pulley. On a dual-cleaner system, a Secondary Cleaner is installed immediately following the Pre- Cleaner to remove stubborn material left on the conveyor belt. If a Pre- Cleaner cannot be used because of space limitations, Secondary Cleaners can be installed alone. Multiple Pre-Cleaners and/or Secondary Cleaners may be required to clean the belt. If the material-handling process or product could be affected by contamination from the use of these belt cleaners, the user is responsible for taking the necessary steps to prevent contamination. Consult Martin Engineering or a representative for alternate belt cleaners or belt cleaner locations to use where contamination may be an issue. |
|------------------------------------|--|
| Installations without chutework | These procedures were written for equipment that is being installed on enclosed pulley chutework. If the pulley is not enclosed, the equipment should be installed using the best available field resources and methods to ensure that the critical dimensions are followed for proper installation. |
| Belt cleaner inspection access | If the belt cleaner is installed on enclosed pulley chutework, at least one Martin [®] Inspection Door should be installed. Martin [®] Inspection Doors are available from Martin Engineering or a representative. |
| Belt cleaner blades | Martin [®] QC1 TM Cleaner HD Blades are available in five different materials (see Table I for specifications). Only standard (orange) Martin [®] QC1 TM Cleaner HD Blades are made of materials that meet Mine Safety and Health Administration (MSHA) requirements under "Interim Fire and Toxicity Criteria for Products Taken Into Underground Mines," March 22, 1977 (MSHA acceptance number MSHA-IC-95/1, MSHA-IC-95/7). |
| References | The following documents are referenced in this manual: |
| | • American National Standards Institute (ANSI) z244.1-1982, American National Standard for Personnel Protection - Lockout/Tagout of Energy Sources - Minimum Safety Requirements, American National Standards Institute, Inc., 1430 Broadway, New York, NY 10018. |
| | • Federal Register, Volume 54, Number 169, Part IV, 29 CFR Part 1910, <i>Control of Hazardous Energy Source (Lockout/Tagout); Final Rule</i> , Department of Labor, Occupational Safety and Health Administration (OSHA), 32nd Floor, Room 3244, 230 South Dearborn Street, Chicago, IL 60604. |
| | • Martin [®] Inspection Door Operator's Manual, P/N M3891 |
| Materials required | Installation of this equipment requires the use of standard hand tools, grinder, welder, and cutting torch. |

| 0 | |
|-----|---|
| tič | ι |
| 5 | S |
| | _ |
| p | |
| 2 | |
| Ð | |
| | |
| | |


Table I. Martin[®] QC1TM Cleaner HD Blade Colors, Materials and Specifications

| URETHANE | APPLICATION DESCRIPTION | TYPICAL | CONTINUOUS |
|---------------|---|--|----------------------------------|
| SELECTION | | MATERIALS | TEMPERATURE |
| Orange | Standard Martin [®] Urethane Suitable for 80% or more of all belt cleaner applications, including abrasive conditions. | Bauxite, Coke, Coal, Overbur- den Refuse | -20° to 160°F (-29° to 71°C) |
| Brown (BR) | Chemical-Resistant Urethane Improves resistance to chemicals; reduced absorption of water in high-moisture environments. | Limestone | -40° to 160°F (-40° to 71°C) |
| Green (GR) | High-Temperature Urethane For exposure to intermittent temperatures up to 350°F (177°C). | Clinker | -40° to 300°F (-40° to 149°C) |
| Clear | Low-Rigidity Urethane | Gravel, | -20° to 160°F |
| (CL) | For dry products such as sand and gravel. | Dry Sand | (-29° to 71°C) |
| Navy Blue | Low-Adhesion Urethane | Cement, Glass, | -20° to 160°F |
| (NB) | For sticky or tacky materials. | Wood Chips | (-29° to 71°C) |

IMPORTANT

Urethane shelf life

Urethane put in service after exceeding it's shelf life may wear differently and deteriorate quicker than normal urethane.






Code Date is written near bottom of blade as mm/dd/yy-x. In addition to or in place of this date, you may see an imprinted date medallion similar to the example shown. In this example, "14" stands for the year 2014. The small circles represent the quarter of the year. If three circles are "punched" the blade was produced in the first quarter. If none of the circles are "punched" the blade was produced in the fourth quarter. If code date on your blade(s) is not legible or is missing, contact Martin Engineering or a representative.

Table II. Urethane Shelf Life

| Blade Color | Shelf Life |
|-------------|------------------------|
| Blue | 1 Year from Code Date |
| Brown | 2 Years from Code Date |
| Clear | 1 Year from Code Date |
| Green | 2 Years from Code Date |
| Orange | 1 Year from Code Date |

N







Do not touch or go near the conveyor belt or conveyor accessories when the belt is running. Your body or clothing can get caught and you can be pulled into the conveyor, resulting in severe injury or death.



Before installing, servicing, or adjusting the belt cleaner, turn off and lockout / tagout / blockout / testout all energy sources to the conveyor and conveyor accessories according to ANSI standards. Failure to do so could result in serious injury or death.





If this equipment will be installed in an enclosed area, test the gas level or dust content before using a cutting torch or welding. Using a torch or welding in an area with gas or dust may cause an explosion resulting in serious injury or death. Follow local confined space procedures.



Before using a cutting torch or welding the chute wall, cover the conveyor belt with a fire retardant cover. Failure to do so can allow the belt to catch fire. Follow local fire watch procedures.





Remove all tools from the installation area and conveyor belt before turning on the conveyor. Failure to do so can cause serious injury to personnel or damage to the belt and conveyor.





Mainframe with blade can be heavy and may require two people to lift. Attempting to lift the belt cleaner without assistance could result in injury.

IMPORTANT

The delivery service is responsible for damage occurring in transit. Martin Engineering CANNOT enter claims for damages. Contact your transportation agent for more information.

- 1. Inspect shipping container for damage. Report damage to delivery service immediately and fill out delivery service's claim form. Keep any damaged goods subject to examination.
- 2. Remove belt cleaner assembly from shipping container.
- 3. If anything is missing contact Martin Engineering or a representative.





Before installing, servicing, or adjusting the belt cleaner, turn off and lockout / tagout / blockout / testout all energy sources to the conveyor and conveyor accessories according to ANSI standards. Failure to do so could result in serious injury or death.

4. Turn off and lockout / tagout / blockout / testout energy source according to ANSI standards (see "References").





If this equipment will be installed in an enclosed area, test the gas level or dust content before using a cutting torch or welding. Using a torch or welding in an area with gas or dust may cause an explosion resulting in serious injury or death. Follow local confined space procedures.

5. If using a cutting torch or welding, test atmosphere for gas level or dust content. Cover conveyor belt with fire retardant cover.

IMPORTANT

Center the belt cleaner blades to clean an area narrower than the conveyor belt width. This allows for side-to-side movement of the belt and prevents damage to the belt edge.



The chute wall that the tensioner will be located on is referred to as the "operator side." The other side of the chute is referred to as the "far side." (If installing dual tensioners, side that is most accessible is "operator side.")

Before Installation




Figure 1. Belt Cleaner Mounting Locations

- 6. Inspect belt cleaner mounting area for possible obstructions that could interfere with proper mounting. Refer to following guidelines:
 - a. The cleaner can be mounted anywhere on the arc from +30 degrees to -30 degrees from a center line parallel to the belt line as long as:
 - (1) The blade is not in the direct flow of discharging material causing premature blade wear.
 - (2) The diameter of the pulley is big enough that the blade does not trap or hold material between the inside of the blade and the belt.
 - (3) There is at least the equivalent of a 45 degree angle between the blade and belt to prevent material buildup in this space.
 - b. Lack of service is the main cause of poor belt cleaning performance. Follow CEMA guidelines for access:
 - (1) Clearance for service outside the chute must be at least equal to the belt width.
 - (2) Cleaners must have service platforms. CEMA recommends cleaners be mounted at least 24 in. (600 mm) above the work platform.
 - (3) If the belt width is 54 in. (1400 mm) or larger consider access doors on both sides of the chute.
 - c. Refer to "Installing Belt Cleaner and Tensioner" and "Part Numbers" sections of this manual for specific mounting and cleaner dimensions.




Figure 2. Belt Cleaner Location

Locating Cleaner Centerline

- 1. On operator side of chute, find pulley center point (A).
- 2. Measure radius of head pulley including lagging and belt thickness (B). To this dimension, add 3.50 in. (89 mm).
- 3. Starting from center point (A), measure the total distance calculated in step 2 (B + 3.50) and draw an arc on chute wall.
- 4. Measure down from pulley's horizontal centerline the distance shown in Figure 2 and draw a horizontal line parallel to it. Locate center point of belt cleaner mainframe (C) where this line intersects the arc on the chute wall.
- 5. Position tensioner on chute wall and align notches in tensioner mount with belt cleaner mainframe centerlines.
- 6. Using the tensioner as a template mark mounting bolt holes.
- 7. Make sure mainframe and blades do not lie in path of material unloading from conveyor belt. Make sure blade tip is at or below horizontal center line.
- 8. Repeat steps 1 through 6 for far side of chute.




Figure 3. Operator Side Chute Cutout




Figure 4. Far Side Chute Cutout

Marking Chute Cutouts

- 1. Using the previously marked lines, mark the operator side chute cutout and mount hole locations as shown in Figure 3. Mark the far side chute cutout and mount hole locations as shown in Figure 4.
 - 2. At the selected mounting positions, cut the cleaner access slots in each side of the chute. Dress and de-burr the cutouts.



Installing Spring Tensioner

For easier maintenance, Martin Engineering recommends bolting rather than welding mount bracket to chute wall.

- 1. Bolt or weld tensioner mount bracket to chute wall as follows:
 - a. If bolting mount bracket to chute wall, do the following:
 - (1) Drill or cut four 5/8-in. holes in operator side chute wall. Remove burrs and sharp edges.
 - (2) Install mount bracket on chute wall with four hex head cap screws, flat washers, compression washers, and hex nuts (M).
 - b. If welding mount bracket to chute wall, do the following:
 - (1) Position mount bracket on chute wall so that four mounting holes line up with four holes marked on chute wall.
 - (2) Weld mount bracket onto chute wall. Skip weld around entire mount bracket surface contacting chute wall.




Figure 5. Adjusting Spring Tensioner

- 2. Tighten nut (A) to adjust spring length according to Table III.
- 3. Tighten jam nut (B) against nut (A).
- 4. Repeat steps 1 and 2 on far side tensioner. Make sure both tensioners are adjusted equally.

| Belt Width in. (mm) | Spring Length in. (mm) |
|------------------------|---------------------------|
| 24 (500–650) | 5.00 (127) |
| 30 (650–800) | 4.75 (121) |
| 36 (800–1000) | 4.50 (114) |
| 42 (1000–1200) | 4.25 (108) |
| 48 (1200–1400) | 4.00 (102) |

Table III. Spring Tensioner Settings

| Belt Width in. (mm) | Spring Length in. (mm) |
|------------------------|---------------------------|
| 54 (1400–1600) | 4.875 (124) |
| 60 (1600–1800) | 4.75 (121) |
| 72 (1800–2000) | 4.50 (114) |
| 84 (2000–2200) | 4.25 (108) |
| 96 (2200–2400) | 4.00 (102) |

Installing Air Cylinder Tensioner



For easier maintenance, Martin Engineering recommends bolting rather than welding mount bracket to chute wall.

- 1. Bolt or weld tensioner mount bracket to chute wall as follows:
 - a. If bolting mount bracket to chute wall, do the following:
 - (1) Drill or cut four 5/8-in. holes in operator side chute wall. Remove burrs and sharp edges.
 - (2) Install mount bracket on chute wall with four hex head cap screws, flat washers, compression washers, and hex nuts (M).
 - b. If welding mount bracket to chute wall, do the following:
 - (1) Position mount bracket on chute wall so that four mounting holes line up with four holes marked on chute wall.
 - (2) Weld mount bracket onto chute wall. Skip weld around entire mount bracket surface contacting chute wall.




Figure 6. Air Cylinder Schematic

2. Install air line to air tensioner as shown in Figure 6.



Make sure you install air line into same port location on far side cylinder as on operator side cylinder.

- a. Install air line from port 1 on 3-way valve into one of two ports on air cylinder (G). Route air line to far side and install in same port on far side air cylinder.
- b. Install air line from port 2 on 3-way valve into unused port on air cylinder. Route air line to far side and install in same port on far side air cylinder.



Do not apply pressures greater than those recommended in Table IV. Higher pressures can damage conveyor belt or cleaner, and blades will wear faster.

3. Apply air pressure to air tensioner(s) according to Table IV.

Table IV. Air Cylinder Tensioner Settings

| Belt Width in. (mm) | Air Pressure psi (bar) |
|------------------------|---------------------------|
| 24 (500–650) | 8 (0.55) |
| 30 (650–800) | 11 (0.76) |
| 36 (800–1000) | 14 (0.97) |
| 42 (1000–1200) | 17 (1.17) |
| 48 (1200–1400) | 19 (1.31) |

| Belt Width in. (mm) | Air Pressure psi (bar) |
|------------------------|---------------------------|
| 54 (1400–1600) | 21 (1.45) |
| 60 (1600–1800) | 24 (1.65) |
| 72 (1800–2000) | 30 (2.07) |
| 84 (2000–2200) | 35 (2.41) |
| 96 (2200–2400) | 41 (2.83) |

Installation




Figure 7. Installing Belt Cleaner

Installing Belt Cleaner

- 1. Install mandrel (A) into tensioners.
- 2. Insert pin (B) to hold mandrel in place.
- 3. Tighten set screws (C).
- 4. If necessary, cut excess mandrel from far side.
- 5. Remove pin (B).
- 6. Slide cartridge with blade (D) onto mandrel.
- 7. Install spacer (E). Insert pin (B) through operator side tensioner, spacer (E), cartridge (D) and mandrel (A).
- 8. Make sure blade is centered on belt and mainframe is parallel to belt.
- 9. If necessary, change location of pins (F and G) to center blade on belt.

After Installing Belt Cleaner



- 1. Thoroughly wipe chute wall clean above tensioner.
- 2. Place Conveyor Products Warning Label (P/N 23395) on outside chute wall visible to belt cleaner operator.
- 3. Additional safety labels are available from CEMA. For more information regarding CEMA safety labels visit www.cemanet.org.



Failure to remove tools from installation area and conveyor belt before turning on energy source can cause serious injury to personnel and damage to belt.

A DANGER

Do not touch or go near conveyor belt or conveyor accessories when conveyor belt is running. Body or clothing can get caught and pull body into conveyor belt, causing severe injury or death.

4. Turn on conveyor belt for 1 hour, then turn off.



Before installing, servicing, or adjusting the belt cleaner, turn off and lockout / tagout / blockout / testout all energy sources to the conveyor and conveyor accessories according to ANSI standards. Failure to do so could result in serious injury or death.

- a. Make sure all fasteners are tight. Tighten if necessary.
- b. Inspect belt cleaner for the following:
 - (1) Wear. (A small amount of "break-in" wear may be found. This will stop once blades wear to conveyor belt contour.)
 - (2) Material buildup. (No material between blades and return side of conveyor belt should be found.)
- c. If wear, material buildup, or some other problem exists, see "Troubleshooting."





Maintenance

IMPORTANT

Read entire section before beginning work.



Maintenance inspections should be performed weekly until a maintenance schedule can be determined. Certain applications and/or changing material conditions may require more frequent maintenance inspections.



Before installing, servicing, or adjusting the belt cleaner, turn off and lockout / tagout / blockout / testout all energy sources to the conveyor and conveyor accessories according to ANSI standards. Failure to do so could result in serious injury or death.

- 1. Remove any material from belt cleaner.
- 2. Make sure all fasteners are tight. Tighten if necessary.
- 3. Check tension on cleaner. Re-tension if necessary.
- 4. Wipe all labels clean. If labels are not readable, contact Martin Engineering or a representative for replacements.
- 5. Check blades for excessive wear. Replace if necessary.
- 6. Remove equipment from service if there is any indication it is not functioning properly. Call Martin Engineering or a representative for assistance. Do NOT return equipment to operation until the cause of the problem has been identified and corrected.

Blade Servicing

- 1. Undo tensioner and visually inspect blades.
 - a. If blades are clean and not excessively worn, re-tension cleaner.
 - b. If material buildup is still present or blades are worn excessively, proceed.



Maintenance




Figure 8. Blade Replacement

- 2. Release tension on each side of cleaner.
- 3. Remove pin (A) and spacer (B).
- 4. Using handle (C) pull cartridge (D) outside the chute just far enough to remove pin (E).
- 5. Remove blade (F).
- 6. Replace blade and install pin (E).
- 7. Slide cartridge (D) back into place.
- 8. Install spacer (B). Insert pin (A) through operator side tensioner, spacer (B), cartridge (D) and mandrel (G).
- 9. Re-tension the cleaner.







Failure to remove tools from installation area and conveyor belt before turning on energy source can cause serious injury to personnel and damage to belt.

10. Remove all tools from maintenance area.



Do not touch or go near conveyor belt or conveyor accessories when conveyor belt is running. Body or clothing can get caught and pull body into conveyor belt, causing severe injury or death.

11. Start conveyor belt.

Troubleshooting

| Symptom | Corrective Action |
|--|---|
| Insufficient cleaning and carryback. | Tension of cleaner on belt is set too low or too high. Increase or decrease tensioner setting. Blades are worn. Check blades and replace if necessary. |
| Blade wears only in the center. | Use a segmented style blade for crown pulleys. Consider narrowing the blade width to clean the middle of the belt. |
| Noise or vibration. | Tension is not sufficient or is set too high. Correct tension as necessary. If this does not correct problem, blade urethane may not match application. Contact Martin Engineering or representative. |
| High blade wear rate. | Tension of cleaner on belt is set too high. Reduce tensioner setting. |
| Unusual wear or damage to blades. | Check belt splice(s) and repair as necessary. |
| Bent or broken mainframe or support frame due to blade slipping through. | If blades are worn to or past the wear line, replace blades. If blades are not worn, check mainframe location. |
| Corrosion or chemical degradation. | Blade urethane may not match application. Contact Martin Engineering or a representative. |



Conveyor equipment such as conveyor belt cleaners are subject to a wide variety of bulk materials characteristics and often have to perform under extreme operating or environmental conditions. It is not possible to predict all circumstances that may require troubleshooting. Contact Martin Engineering or a representative if you are experiencing problems other than those listed in the "Troubleshooting" chart above. Do not return the equipment to operation until the problem has been identified and corrected.

Installation If after taking the corrective actions suggested under "Troubleshooting" you are still experiencing problems, check for the following:

Installation Checklist

- ✓ Pre-Cleaner mainframe is proper distance from belt surface on both ends of mainframe and parallel to the pulley shaft.
- ✓ Pre-Cleaner blade tip does not lie in path of material flow.
- ✓ Blades are centered on belt.


This section provides product names and corresponding part numbers for Martin[®] QC1TM Cleaner XHD STS and related equipment. Please reference part numbers when ordering parts:

Martin[®] QC1™ Cleaner ĤD STS

| Cieuner IID 515 | NOMENCLATURE STSXHDQC | - <u>xx xx xx xx x</u> |
|-----------------|---|---|
| | P/N Prefix Belt Width (inches) Slits/Segments Blade Width (inches) Urethane Color Tensioner and Mandrel Tube | |
| | SLITS/SEGMENTS 11: No slits or segments 10: Segments only 01: Slits only 00: Slits & Segments | URETHANE COLOR B1: Black BR: Brown CL: Tan GR: Green |
| | TENSIONER T : Martin [®] STS Tensioner Blank: No Tensioner or Mandrel Tube | NB: Navy Blue CY: Yellow with Beads YL: Yellow Blank: Orange |
| Tensioners | Martin [®] Spring Tensioner HD STS | : P/N 39100-HDS |

Martin[®] Air Cylinder Tensioner HD STS: P/N 39100-HDA

Part Numbers



| Item | Description | Part no. | Qty |
|---------|-----------------------------------|------------|-----|
| 1 | Mainframe Weldment | 39375-XX* | 1 |
| 2 | Blade | Table V | 1 |
| 3 | Frame Mandrel | 39376-XX* | 1 |
| 4 | Pin Slotted Spring 5/16 x 2 ZP | 32774 | 1 |
| 5 | Pin Wire Lock 1/4 x 2-1/2 | 32772 | 1 |
| 6 | Handle Weldment | 39242-2_5 | 1 |
| 7 | Washer Flat 3/8 wide ZP | 18007 | 2 |
| 8 | Screw HHC 3/8-16NC x 3-3/4 ZP | 16098 | 1 |
| 9 | Nut Hex Elastic Lock 3/8-16NC ZP | 14201 | 1 |
| 10 (NS) | Label Martin [®] Product | 38048 | 2 |
| 11 (NS) | STS HD Spring Tensioner | 39100-HDSX | 1 |

| Item | Description | Part no. | Qty |
|---------|---------------------------------|-----------|-----|
| 12 (NS) | STS HD Air Cylinder Tensioner | 39100-HDA | 1 |
| 13 (NS) | Operator's Manual | M4043 | 1 |
| 14 (NS) | Label Conveyor Products Warning | 23395 | 2 |

*XX indicates belt width.

NS = Not Shown

Table V. Martin[®] QC1TM Cleaner HD STS Assembly Part Numbers

| Part No. | Dim A Blade Length | Dim B Frame Length | Dim C Frame Length | Part No. Item 2 |
|-------------------|-----------------------|-----------------------|-----------------------|--------------------|
| STSHDQC-24XX16XXX | 16.00 (406) | 38.50 (978) | 55.00 (1397) | 35381-24XX16XX |
| STSHDQC-24XX18XXX | 18.00 (457) | 38.50 (978) | 55.00 (1397) | 35381-24XX18XX |
| STSHDQC-24XX22XXX | 22.00 (559) | 38.50 (978) | 55.00 (1397) | 35381-24XX22XX |
| STSHDQC-30XX22XXX | 22.00 (559) | 44.50 (1130) | 61.00 (1549) | 35381-30XX22XX |
| STSHDQC-30XX24XXX | 24.00 (610) | 44.50 (1130) | 61.00 (1549) | 35381-30XX24XX |
| STSHDQC-30XX28XXX | 28.00 (711) | 44.50 (1130) | 61.00 (1549) | 35381-30XX28XX |
| STSHDQC-36XX28XXX | 28.00 (711) | 50.50 (1283) | 67.00 (1702) | 35381-36XX28XX |
| STSHDQC-36XX30XXX | 30.00 (762) | 50.50 (1283) | 67.00 (1702) | 35381-36XX30XX |
| STSHDQC-36XX34XXX | 34.00 (864) | 50.50 (1283) | 67.00 (1702) | 35381-36XX34XX |
| STSHDQC-42XX34XXX | 34.00 (864) | 56.50 (1435) | 73.00 (1854) | 35381-42XX34XX |
| STSHDQC-42XX36XXX | 36.00 (914) | 56.50 (1435) | 73.00 (1854) | 35381-42XX36XX |
| STSHDQC-42XX40XXX | 40.00 (1016) | 56.50 (1435) | 73.00 (1854) | 35381-42XX40XX |
| STSHDQC-48XX40XXX | 40.00 (1016) | 62.50 (1588) | 79.00 (2007) | 35381-48XX40XX |
| STSHDQC-48XX42XXX | 42.00 (1067) | 62.50 (1588) | 79.00 (2007) | 35381-48XX42XX |
| STSHDQC-48XX46XXX | 46.00 (1168) | 62.50 (1588) | 79.00 (2007) | 35381-48XX46XX |
| STSHDQC-54XX46XXX | 46.00 (1168) | 68.50 (1740) | 85.00 (2159) | 35381-54XX46XX |
| STSHDQC-54XX48XXX | 48.00 (1219) | 68.50 (1740) | 85.00 (2159) | 35381-54XX48XX |
| STSHDQC-54XX52XXX | 52.00 (1321) | 68.50 (1740) | 85.00 (2159) | 35381-54XX52XX |
| STSHDQC-60XX52XXX | 52.00 (1321) | 74.50 (1892) | 91.00 (2311) | 35381-60XX52XX |
| STSHDQC-60XX54XXX | 54.00 (1372) | 74.50 (1892) | 91.00 (2311) | 35381-60XX54XX |
| STSHDQC-60XX58XXX | 58.00 (1473) | 74.50 (1892) | 91.00 (2311) | 35381-60XX58XX |
| STSHDQC-66XX58XXX | 58.00 (1473) | 80.50 (2045) | 97.00 (2464) | 35381-66XX58XX |
| STSHDQC-66XX60XXX | 60.00 (1524) | 80.50 (2045) | 97.00 (2464) | 35381-66XX60XX |
| STSHDQC-66XX64XXX | 64.00 (1626) | 80.50 (2045) | 97.00 (2464) | 35381-66XX64XX |
| STSHDQC-72XX64XXX | 64.00 (1626) | 86.50 (2197) | 103.00 (2616) | 35381-72XX64XX |
| STSHDQC-72XX66XXX | 66.00 (1676) | 86.50 (2197) | 103.00 (2616) | 35381-72XX66XX |
| STSHDQC-72XX70XXX | 70.00 (1778) | 86.50 (2197) | 103.00 (2616) | 35381-72XX70XX |

Part Numbers




Figure 10. Martin[®] Air Cylinder Tensioner HD STS, P/N 39100-HDA

| Item | Description | Part no. | Qty |
|---------|--|-----------|-----|
| 1 | Operator Side Mount Weldment | 39094-HDR | 1 |
| 2 | Far Side Mount Weldment | 39094-HDL | 1 |
| 3 | Spacer Tube | 39097 | 10 |
| 4 | Slider Outer Ring | 39098-HD | 2 |
| 5 | Washer Compression 1/2 SS | 24310 | 14 |
| 6 | Screw HHC 1/2-13NC x 2 SS | 24308 | 10 |
| 7 | Saddle Pivot Weldment | 39093-HD | 1 |
| 8 | Saddle Pivot Weldment | 39093-HDM | 1 |
| 9 | Plastic Bumper | 39092 | 24 |
| 10 | Screw SPHM #6-32 x 7/8 SS | 39136 | 12 |
| 11 | Washer Lock Helical Spring #6 SS | 39137 | 12 |
| 12 | Nut Hex Undersized Mach #6-32 SS | 39138 | 12 |
| 13 | Far Side Strap Weldment | 39090-HD | 1 |
| 14 | Screw SHS 1/2-13NC x 1-1/2 SS | 33190 | 3 |
| 15 | HD Cartridge Spacer | 39134F-HD | 1 |
| 16 | Hitch Pin w/Lynch Pin/Chain 1/2 x 5.75 | 35876 | 1 |
| 17 | Air Cylinder 3.25 Bore x 5.00 Stroke | 32130-2 | 2 |
| 18 | Air Cylinder Rod Eye 3/4-16NF | 32131-2 | 2 |
| 19 | Air Cylinder Rod Eye Tube | 39094-6A | 2 |
| 20 | Air Cylinder Trunnion Mount Angle Weldment | 39094-12A | 2 |
| 21 (NS) | Label Martin Product | 32238 | 2 |
| 22 | Screw HHC 1/2-13NC x 2-3/4 SS | 26155 | 2 |
| 23 | Nut Hex 1/2-13NC SS | 17151 | 2 |
| 24 | Screw HHC 3/8-16NC x 1 SS | 11461 | 4 |
| 25 | Washer Compression 3/8 SS | 28565 | 4 |
| 26 | Nut Hex 3/8-16NC SS | 16054 | 4 |
| 27 (NS) | Label Conveyor Products Warning | 23395 | 2 |
| 28 (NS) | Mounting Hardware | 38228-SS | 1 |
| 29 (NS) | Operator's Manual | M3987 | 1 |
| 30 (NS) | Label Tensioning | 39437-A | 1 |

Figure 10. Martin[®] Air Cylinder Tensioner HD STS, P/N 39100-HDA

Part Numbers




Figure 11. Martin[®] Spring Tensioner HD STS, P/N 39100-HDS

| Item | Description | Part no. | Qty |
|---------|--|-----------|-----|
| 1 | Operator Side Mount Weldment | 39094-HDR | 1 |
| 2 | Far Side Mount Weldment | 39094-HDL | 1 |
| 3 | Spacer Tube | 39097 | 10 |
| 4 | Slider Outer Ring | 39098-HD | 2 |
| 5 | Washer Compression 1/2 SS | 24310 | 14 |
| 6 | Screw HHC 1/2-13NC x 2 SS | 24308 | 10 |
| 7 | Saddle Pivot Weldment | 39093-HD | 1 |
| 8 | Saddle Pivot Weldment | 39093-HDM | 1 |
| 9 | Plastic Bumper | 39092 | 24 |
| 10 | Screw SPHM #6-32 x 7/8 SS | 39136 | 12 |
| 11 | Washer Lock Helical Spring #6 SS | 39137 | 12 |
| 12 | Nut Hex Undersized Mach #6-32 SS | 39138 | 12 |
| 13 | Far Side Strap Weldment | 39090-HD | 1 |
| 14 | Screw SHS 1/2-13NC x 1-1/2 SS | 33190 | 3 |
| 15 | HD Cartridge Spacer | 39134F-HD | 1 |
| 16 | Hitch Pin w/Lynch Pin/Chain 1/2 x 5.75 | 35876 | 1 |
| 17 | Spring Stop | 39377-01 | 2 |
| 18 | Threaded Rod Weldment | 39377-03 | 2 |
| 19 | Washer Flat 3/4 Military Spec SS | 16223 | 4 |
| 20 | Spring Compression | Table I | 2 |
| 21 | Nut Hex 3/4-6 Acme 304 SS | 38170-SS | 4 |
| 22 | Air Cylinder Rod Eye Tube | 39094-6A | 2 |
| 23 | Air Cylinder Trunnion Mount Angle Weldment | 39094-12A | 2 |
| 24 (NS) | Label Martin Product | 32238 | 2 |
| 25 | Screw HHC 1/2-13NC x 2-3/4 SS | 26155 | 2 |
| 26 | Nut Hex 1/2-13NC SS | 17151 | 2 |
| 27 | Screw HHC 3/8-16NC x 1 SS | 11461 | 4 |
| 28 | Washer Compression 3/8 SS | 28565 | 4 |
| 29 | Nut Hex 3/8-16NC SS | 16054 | 4 |
| 30 (NS) | Label Conveyor Products Warning | 23395 | 2 |
| 31 (NS) | Mounting Hardware | 38228-SS | 1 |
| 32 (NS) | Operator's Manual | M3987 | 1 |
| 33 (NS) | Label Tensioning | 39437-S | 1 |

| Figure 11. Martin [@] | [®] Spring Tensioner | HD STS. P/N | 39100-HDS |
|--------------------------------|-------------------------------|-------------|--------------------|
| riguit 11. Martin | Spring rensioner | 110 515,171 | 37100-11D 5 |




Figure 12. Martin[®] Conveyor Products Warning Label, P/N 23395



Figure 13. Martin[®] Pinch Point Warning Label, P/N 30528

| Ν | lartin [®] Spring ⁻ Recommer | Tensioner HD nded Tension | STS | |
|-----|---|------------------------------|-------|-------------------------------------|
| E | Belt Width | Compres Spring Le | | |
| in. | (mm) | in. | (mm) | |
| 24 | (500-650) | 5.00 | (127) | |
| 30 | (650-800) | 4.75 | (121) | |
| 36 | (800-1000) | 4.50 | (114) | |
| 42 | (1000-1200) | 4.25 | (108) | |
| 48 | (1200-1400) | 4.00 | (102) | |
| 54 | (1400-1600) | 4.875 | (124) | |
| 60 | (1600-1800) | 4.75 | (121) | |
| 72 | (1800-2000) | 4.50 | (114) | |
| 84 | (2000-2200) | 4.25 | (108) | |
| 96 | (2200-2400) | 4.00 | (102) | |
| | *Per tensioner. Dua | al tensioners require | d. | - |
| | | | | |
| | or 30 | -544-2947)9-852-2384 | | l on chute wall, tensioner user. |
| | www.n | nartin-eng.com | Labe | el P/N 39437-S |


Figure 14. Martin[®] Spring Tensioner HD STS Tensioning Label, P/N 39437-S

| E | Belt Width | Air Pres | ssure* |
|-----|--------------------|---------------------|--------|
| in. | (mm) | psi | (bar) |
| 24 | (500-650) | 8 | (0.55) |
| 30 | (650-800) | 11 | (0.76) |
| 36 | (800-1000) | 14 | (0.97) |
| 42 | (1000-1200) | 17 | (1.17) |
| 48 | (1200-1400) | 19 | (1.31) |
| 54 | (1400-1600) | 21 | (1.45) |
| 60 | (1600-1800) | 24 | (1.65) |
| 72 | (1800-2000) | 30 | (2.07) |
| 84 | (2000-2200) | 35 | (2.41) |
| 96 | (2200-2400) | 41 | (2.83) |
| | *Per tensioner. Du | al tensioners requi | red. |

Figure 15. Martin[®] Air Tensioner HD STS Tensioning Label, P/N 39437-A

Any product, process, or technology described here may be the subject of intellectual property rights reserved by Martin Engineering Company. Trademarks or service marks designated with the ® symbol are registered with the U.S. Patent and Trademark Office and may be proprietary in one or more countries or regions. Other trademarks and service marks belonging to Martin Engineering Company in the United States and/or other countries or regions may be designated with the "TM" and "SM" symbols. Brands, trademarks, and names of other parties, who may or may not be affiliated with, connected to, or endorsed by Martin Engineering Company, are identified wherever possible. Additional information regarding Martin Engineering Company's intellectual property can be obtained at www.martin-eng.com/trademarks.





For nearly 20 years, Martin Engineering's Foundations[™] Books have taught industry personnel to operate and maintain clean and safe belt conveyors. The Foundations[™] Book, fourth edition, focuses on improving belt conveyors by controlling fugitive material. "The Practical Resource for Total Dust and Material Control," is a 576-page hard cover volume that provides information of value to industries where the efficient handling of bulk materials is a key to productivity and profitability.

Expanding upon the book, our Foundations[™] Training Program addresses the design and development of more productive belt conveyors, and is offered in three customizable seminars. Attendees gain a better understanding of conveyor safety and performance, helping to justify upgrade investments and increase profitability.



Martin Engineering USA One Martin Place Neponset, IL 61345-9766 USA 800 544 2947 or 309 852 2384 Fax 800 814 1553 www.martin-eng.com

COMPANY WITH QUALITY SYSTEM CERTIFIED BY DNV = ISO 9001:2008 =