



QUARTER 3 | 2022

22

Rooikraal Quarry's closed water circuit

28

Lifetime costs of fabricated parts for vibrating screens



CONTENTS







Efficiency and reliability PAGE 26



Fabricating failure: examining the lifetime costs of fabricated parts for vibrating screens $\,\textbf{PAGE 28}\,$



SAFE AND RESPONSIBLE DUST SUPPRESSION

Modern Quarrying spoke to Michelle Fick, CHRYSO Southern Africa's Business Development for Concrete Aesthetics & Key Account Manager about its Eco Dust range.





MEASURING TO MANAGE: LOAD WEIGHING SYSTEMS SET THE STANDARD

In the current cut-throat quarrying industry with its slim margins, operations need to be as effective and accurate as possible when the weight of mined aggregate is determined.





INDUSTRY

- 32 Hillhead 2022: back with a bang
- 33 Cleaner and alternative energy solutions crucial for future of mining
- **34** UN warns of worldwide sand shortage

SUPPLY CHAIN

- 35 Sandvik customers welcome new crushing solutions
- **36** Solutions in delivering optimal uptime for the connected mine
- 38 Beowolf Mining to launch new products at Electra Mining
- **40** New Lokotrack LT200hpx increases capacity by up to 30%



NO JOKE: KNOCK-KNOCK ON CONVEYOR IDLERS

On any belt conveyor system that moves bulk materials, the belt must run straight and true to maximise its life, minimise fugitive material and safety hazards, and achieve high system efficiency. There can be many consequences of a mistracking belt, but all result in higher costs and increased maintenance. Even a slight belt misalignment can lead to a variety of issues, from small annoyances to full-blown catastrophes. By Cory Goldbeck - Territory Manager, Martin Engineering

he most obvious effects include spillage and dust that require personnel to do cleanup, which is unproductive work that introduces risks from activities in close proximity to the moving conveyor. Spillage from non-centered cargo often gets into idlers and pulleys, reducing bearing life and causing them to seize, leading to friction damage

on the belt and potentially starting a fire. A misaligned belt can also come in contact with the stringer, causing fraying, shredding or splice damage. Great lengths of valuable belting can be destroyed with surprising speed, and even the support structure itself can be damaged. A compromised bracket or support can cause a catastrophic idler failure, which could damage other components of the system

and require extensive downtime to repair. Further, there is potential for injury from a damaged belt or loose idler not to mention the increased exposure to injury from too frequent a need to clean.

"I've been working around conveyors for 20 years, and I've seen thousands of belts," observed Martin Engineering Process Engineer Dan Marshall. "I've seen just about every problem that can





Multi-Pivot Trainer for the load-carrying run.



A tracking idler tied off to limit its travel.

nartin Engineering Com shotographs.

KEY TAKEAWAYS



A compromised bracket or support can cause a catastrophic idler failure, which could damage other components of the system and require extensive downtime to repair.



Multi-Pivot Belt Trainers use longer arms than other designs, positioning the guide rolls further from the pivot roller, as well as closer to the belt edge.



Specific designs are available for both the loadcarrying belt path and the return run.




Installing trackers is the economical solution, but operators should do a full analysis and consider also addressing other causal issues.

be caused by a mistracking belt, but one thing I've never seen is a belt that runs true right out of the box. All conveyors, no matter how well designed and built, have some belt wander."

A wide variety of circumstances can lead to mistracking, and operators have tried many things to correct the alignment. Some have elected to place an obstacle such as a block of wood in the belt path, so it won't travel too far out of line. This occasionally improves the situation, but more often it's just temporary and the belt will eventually slice through the obstacle.

Many operators have realised that pivoting an idler is a quicker and more effective way to steer a belt. This common approach is called "knocking an idler," striking it with a hammer to move it slightly and realign the belt.

Equipment manufacturers have also designed components to help align a belt, and these solutions



Different component designs for improving belt alignment.



"Knocking" an idler with a mallet to change its position.

can be successful in specific applications. They include specially-shaped rollers, angled idlers and devices that apply pressure to the belt edge to push it back in line.

"While these mechanisms can improve a belt that's consistently off-center in one direction, they do not react to dynamic belt movement, meaning that they don't correct intermittent belt wander," Marshall continued. "To combat such changing conditions, engineers designed the tracking idler. Unlike the edge correction approach, the device senses belt movement in either direction, and pivots the idler slightly to steer the belt back into position. It doesn't apply a great deal of force to the edges, which can damage a belt and splices. When the belt is running true, it remains centered, and when it senses a misaligned condition, it gently corrects the belt."

Unfortunately, to accommodate limited space availability, tracking idlers typically have short sensing arms. This requires a fairly large belt displacement to create a small movement of the idler. While these



designs do tend to improve tracking, there are limits to how much correction they can deliver, and short sensing arms can actually pinch a belt if the idler pivots too far. To combat this, some operators choose to "tie off" a tracking idler to limit its movement. While the practice can help preserve the belt, it doesn't address significant mistracking.

To overcome the limitations of existing belt alignment devices, Martin Engineering has invented and patented a Multi-Pivot Belt Tracker, which employs sensors, pivoting idlers and geometry to align a wandering belt. The sensors avoid pinching the belt, and the engineered geometry amplifies any detected

misalignment to create a greater pivot.

Multi-Pivot Belt Trainers use longer arms than other designs, positioning the guide rolls further from the pivot roller, as well as closer to the belt edge. The closer proximity allows guide rolls to sense very slight misalignments and make immediate corrections. Rather than waiting for a powerful mistracking force, the longer arms require considerably less pressure to move the pivot roller. The result is better correction with no pinch points and less wear on conveyor and tracking equipment, for a longer and more efficient service life. Specific designs are available for both the load-carrying belt path and the return run.

"Installing trackers is the economical solution, but operators should do a full analysis and consider also addressing other causal issues," Marshall added. "By focusing solely on belt alignment, plant personnel may miss other opportunities to increase production and relieve some of the burden on their system."

Keeping the belt centered and moving quickly is the key to high production, controlled operating cost and a safer workplace.
"Misalignment causes downtime and costs money," Marshall concluded.
"But nothing causes more downtime and expense than a destructive belt fire or other catastrophe as a result of inattention to mistracking problems."

Martin Engineering is a global innovator in the bulk material handling industry, developing new solutions to common problems and participating in industry organisations to improve safety and productivity. The company's series of Foundations books is an internationally-recognised resource for safety, maintenance and operations training – with more than 2 000 print copies in circulation around the world. The entire 500+ page volumes can also be downloaded as free PDFs from the Martin web site. Martin Engineering products, sales, service and training are available from 19 factory-owned facilities worldwide, with wholly-owned business units in Australia, Brazil, Chile, China, Colombia, France, Germany, India, Indonesia, Italy, Japan, Mexico, Peru, Russia, Spain, South Africa, Turkey, the USA and UK.